

## 职业卫生评价项目信息网上公开表

公示时间：2023年9月26日

用人单位 (建设项目)名称	民权县新联加油站	联系人	李振
地理位置	河南省商丘市民权县孙六镇龙门大道中段东侧。		
项目名称	民权县新联加油站职业病危害现状评价		
项目简介	民权县新联加油站成立于2023年1月11日，法人代表为邓桂林，主要储存、经营车用乙醇汽油、柴油。		
项目负责人	王伟超		
现场调查人	王伟超、刘素宾		
现场调查时间	2023.9.10	用人单位陪同人	李振
现场采样、检测人员	王伟超、王刚		
采样、检测 时间	2023.9.15~2023.9.17	用人单位陪同人	李振
报告完成日期	2023.9.26	报告编号	DX/XP-ZP230901
用人单位 (建设项目)存在的职业 病危害因素及检 测结果	存在的职业病危害因素：苯、甲苯、二甲苯、溶剂汽油、噪声 检测结果：用人单位各工种接触的职业病危害因素浓度/强度均不超过职业接触限值		
评价结论与建议	结论：用人单位各工种接触的职业病危害因素浓度/强度均不超过职业接触限值。用人单位总体布局、生产工艺与设备布局符合要求；建筑物采光照度、通风与空气调节、采暖满足卫生要求；职业病危害的浓度和强度不超标；职业病危害防护设施有一定的防护效果，达到相关标准要求；正在筹备职业健康检查工作；个体防护用品发放及时，防护用品合格；辅助用室的设置符合相关法律、法规的要求；职业卫生管理制度相对完善，但未开展工作场所职业病危害因素进行日常监测工作，未进行职业病危害申报，职业卫生档案内容不完善。 建议：（1）做好储油罐、出油管线、加油机、油气回收装置等装置的检查、维护工作，发现损坏时及时修理或更换。		

	<p>(2) 按照《职业健康监护规范》(GBZ188-2014)的规定,规范开展上岗前、在岗期间和离岗时职业健康检查工作。</p> <p>(3) 购置苯、甲苯、二甲苯、汽油、噪声的日常监测设备或委托第三方机构进行职业病危害因素日常监测工作,及时将监测结果进行公告。按照《工作场所职业卫生管理规定》的要求开展工作场所职业危害因素定期检测工作。</p> <p>(4) 及时进行职业病危害项目申报。</p> <p>(5) 按照《职业卫生档案管理规范》(安监总厅安健〔2013〕171号)完善职业卫生档案内容,并将职业卫生日常管理过程资料及时存入职业卫生档案。</p>
技术审查专家组 评审意见	—
现场影像资料	 <p>The '现场影像资料' (On-site Image Material) section contains four photographs. The top-left photo shows two men standing in front of a '新联石油' (New Union Oil) gas station. The top-right photo shows a white car at a gas pump under the station's canopy. The bottom-left photo shows an industrial facility with a tall chimney and various structures. The bottom-right photo shows another view of the '新联石油' gas station building and canopy.</p>